

Manhole Inspection Summary

Manhole # S11Q__022MH

Printed On: 2/20/2009

Page 1 of 4

Inspection ☐ Is Incomplete Rating: **4) Poor**

Record Plat: **11Q** Node: **022** Status: **Other (Specify in comment)** Insp Date: **12/23/08 12:51 PM**

Incomplete Comments

Crew:
Inspector: **bharris**
Firm:

Location Address:

Cross Street:

Manhole Type:

Location:

Ground Conditions:

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **Abandoned!!**

Cover

Shape:

Diameter: **0** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary**

Condition:

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame

Offset: **0** (in.)

Condition: ☐ Sound ☐ Cracked ☒ **Leaks**

Chimney / Frame Adjustment

☐ Exists

Material:

☐ Parged Height: **0** (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel

Material:

☐ Parged

Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☒ **Loose Brick** ☐ Deteriorated

Infiltration: ☐ None ☒ **Joint** ☐ Cracks ☐ Mortar ☐ Roots ☒ **Wall**

Barrel

Material:

☐ Parged

Shape:

Diameter: **0** (in.) Length: **0** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☒ **Wall**

Bench

☐ Exists Material:

☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel

Material:

☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps

Count: **0** Missing: **0** ☒ **Corroded**

Surcharge

☐ Evidence Of Surcharge

Depth: **0** (ft.) ☐ Active Surcharge Present

Manhole Inspection Summary

Manhole # S11Q__022MH

Printed On: 2/20/2009

Page 2 of 4

Location View



Top View



Defect 4



missing bricks and mortar at corbel with infiltration

Defect 3



frame leaks

Defect 2



steps corroded

Defect 1



barrel flow wall

Manhole Inspection Summary

Manhole # S11Q__022MH

Printed On: 2/20/2009

Page 3 of 4

10 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **10.8** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** ☐ Pipe Lined
Invert Depth: **15.82** (ft.) Flow Characteristics: **None**
Deposits: ☐ None ☐ Mud ☒ **Grout** ☐ Debris ☐ Grease
Silt Depth: **4** (in.) Deposits Extent: **Medium**
Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

0 in. Circular Gravity Sewer
Pipe In @ 3 O'Clock

3 O'Clock Inflow



conc plugged opng

Pipe Height: **0** (in.)
Pipe Material: ☐ Pipe Lined
Invert Depth: **0.00** (ft.) Flow Characteristics:
Deposits: ☐ None ☐ Mud ☒ **Grout** ☐ Debris ☐ Grease
Silt Depth: **4** (in.) Deposits Extent: **Medium**
Infiltration: Pipe Seal Cond:

Drop:
Angled: Reading: **0.00** (ft.)
Inv Depth: **0.00** (ft.)

Drop Condition:

Connects To: **Stub connection / abandoned**

☐ Possible Illicit Connection

Manhole Inspection Summary

Manhole # S11Q__022MH

Printed On: 2/20/2009

Page 4 of 4

0 in. Circular Gravity Sewer

5 O'Clock Inflow

Pipe In @ 5 O'Clock



conc plugged opng

Pipe Height: 0 (in.)

Pipe Material: ☐ Pipe Lined

Invert Depth: 0.00 (ft.) Flow Characteristics:

Deposits: ☐ None ☐ Mud ☒ Sludge ☐ Debris ☐ Grease

Silt Depth: 4 (in.) Deposits Extent: Medium

Infiltration: Pipe Seal Cond:

Drop:

Angled: Reading: 0.00 (ft.)

Inv Depth: 0.00 (ft.)

Drop Condition:

Connects To: Stub connection / abandoned

☐ Possible Illicit Connection

8 in. Circular Gravity Sewer

9 O'Clock Inflow

Pipe In @ 9 O'Clock



Pipe Height: 8.4 (in.) Rod and Bar (Angled)

Pipe Material: Clay ☐ Pipe Lined

Invert Depth: 9.50 (ft.) Flow Characteristics: None

Deposits: ☐ None ☐ Mud ☒ Sludge ☐ Debris ☐ Grease

Silt Depth: 6 (in.) Deposits Extent: Heavy

Infiltration: None

Pipe Seal Cond: Sound

Drop In @ 9 O'Clock



Drop: Outside Rod and Bar

Angled: Yes Reading: 14.60 (ft.)

Inv Depth: 15.60 (ft.)

Drop Condition: Partly Clogged

Connects To: House connection / Service line

☐ Possible Illicit Connection